

CONTENTS

Foreward	vii
Preface	ix
Symbols	xi

1 Introduction 1

The Electromagnetic Spectrum	1
Other Applications of the Quartz Crystal Unit	1
The Piezoelectric Effect	2
Crystals	3
Quartz	4
Historical Review	5
The Piezoelectric Resonator	7
Fabrication Techniques	8
Summary	9

2 The Physical Crystallography of Quartz 11

Anisotropy	11
The Quartz Crystal	12
Crystal Axes and Axial Systems	12
The Z-Axis and Optical Twinning	14
The X-Axis and Electrical Twinning	15
The Y-Axis	17
Specification of Atomic Planes in Crystals	17
Cultured Quartz	20
Growth of Cultured Quartz	20
Orientation	22
Defects in Quartz	23
Symmetry Relations in Crystals	24
The Elements of Matrix Algebra	25
Rotation of Axes	29
The Dielectric Constant and Thermal Expansion	33

xiv CONTENTS

3 Stress and Strain Relationships 38

- Definitions of Stress and Strain 38
- Definitions of the Stress-Strain Relationships 42
- The Generalized Stress-Strain Relationships 43
- Thermal Stresses and Strains 47
- The Elastic Coefficients of Alpha Quartz (Table) 49

4 The Piezoelectric Effect 50

- Introduction 50
- Theory of Piezoelectricity 50
- The Converse Piezoelectric Effect 55
- The Generalized Piezoelectric Equations 56
- The Piezoelectric Matrix for Quartz 60
- The Piezoelectric Coefficients of Alpha Quartz (Table) 62

5 Mechanical Vibrations 63

- Introduction 63
- Function of the Piezoid in Oscillator Circuits 63
- One-dimensional Vibrations 64
- The Vibrating Bar 68
- Two-dimensional Vibrating Systems 69
- Three-dimensional Vibrating Systems (Rectangular Plates) 72
- Three-dimensional Vibrating Systems (Circular Plate) 76
- Summary 80

6 Equivalent Circuit of the Quartz Resonator 82

- Introduction 82
- The Quartz Resonator as a Vibrating Capacitor 83
- Derivation of the Equivalent Circuit 86

7 The Crystal Unit as a Circuit Component 101

- Introduction 101
- The Resonant Frequencies 102
- The Impedances at the Resonant Frequencies 104
- The Parameters of the Equivalent Circuit 105
- Measurement of the Circuit Parameters C_0 and R 106
- Measurement of L and C 107
- The Crystal Unit in Series with a Capacitor 108

	The Problem of Oscillator Correlation	111
	The CI-Meter	112
	Passive-network Methods	114
	The Effect of Shunt Capacitance	117
	Limiting Condition for Oscillation	118
	The Importance of Q	119
	The Critical Frequencies of the Quartz Resonator	120
	The Frequencies of Zero Phase	120
	Frequencies of Maximum and Minimum Impedance	123
	The Impedance Diagram	125
	The Admittance Diagram	126
	Admittance Diagram of the Piezoelectric Resonator	129
8	The Frequency Constants and Temperature Coefficients of Frequency	134
	Introduction	134
	The Frequency Constants (Table)	136
	Linear Coefficients	136
	The Temperature Coefficient of Frequency	137
9	Coupled Modes and Activity Dips	148
	Activity	148
	Activity Dips	148
	Coupling in Vibrating Systems	150
	Coupling by Common Electric Excitation	151
	Coupling by Mechanical or Elastic Excitation	152
	Vibration in Mounting Structures	155
	Coupling through Common Boundary Conditions	155
	Effects of Temperature	157
	Dimensioning	158
	Low Dimensional Ratios	158
10	Inharmonic Overtones and Filter Crystals	160
	Introduction	160
	Nature of the Inharmonic Overtone Modes	160
	The Geometry of the Piezoid	161
	The Fundamental, or $n01$, Mode	162
	The First-Inharmonic Overtone, or $n11$, Mode	163
	The $n02$ Mode	164
	The Effects of Contouring	165
	Energy Trapping	168

xvi CONTENTS

11 X-Rays and X-Ray Orientation 178

- Introduction 178
- Nature and Production of X-Rays 179
- Bragg Diffraction 180
- Care in the Use of X-Rays 183
- Single-Crystal X-Ray Diffraction System 184
- Double-Crystal X-Ray Diffraction System 185
- Preparation of Crystal Standards and Collimating Crystals 189
- Angle Measurements by X-Ray Diffraction 189
- Angle Measurements when the Atomic Planes Do Not Contain the Goniometer Axis 191
- The Effect of Rotation in the Plane of the Blank 193
- Checking Doubly Rotated Blanks by X-Ray Diffraction 194
- Errors Due to Misalignment of the Incident Beam 199
- Derivation of Eqs. (107) to (110) 200
- Derivation of Eqs. (111) and (112) 204

12 Aging in Quartz Crystal Units 208

- Introduction 220
- History of the SC-Cut 222
- Fabrication of the SC-Cut 223
- Characteristics of the SC-Cut 227
- Testing SC-Cut Units 230
- References 232
- Aging Associated with Holder Defects 217
- Accelerated Aging Tests 218
- Methods of Minimizing Aging in Quartz Crystal Units 219

13 The Stress-Compensated Crystal Unit 220

- Introduction 220
- History of the SC-Cut 222
- Fabrication of the SC-Cut 223
- Characteristics of the SC-Cut 227
- Testing SC-Cut Units 230
- References 232

APPENDIX I Basic Dielectric Theory 233

APPENDIX II Complex Numbers 238

APPENDIX III Measuring Techniques	241
APPENDIX IV The Piezoelectric Coupling Coefficient	245
APPENDIX V Glossary	248
APPENDIX VI Problems and Questions	252
BIBLIOGRAPHY	258
INDEX	261