

Contents

<i>Chapter</i>	Introduction, by R. A. Heising.....	1
I.	Quartz Crystal Applications, by W. P. Mason.....	11
	Appendix A—Voigt's Elastic and Piezoelectric Relations and Their Application to the Determination of Low Temperature Coefficient Crystals.....	34
II.	Methods for Specifying Quartz Crystal Orientation and Their Determination by Optical Means, by W. L. Bond.....	57
	Appendix B—The Ring Eccentricity Correction.....	91
III.	The Use of X-Rays for Determining the Orientation of Quartz Crystals, by W. L. Bond and E. J. Armstrong.....	95
IV.	Raw Quartz, Its Imperfections and Inspection, by G. W. Willard.....	140
V.	Use of the Etch Technique for Determining Orientation and Twinning in Quartz Crystals, by G. W. Willard.....	164
VI.	Modes of Motion in Quartz Crystals, the Effects of Coupling and Methods of Design, by R. A. Sykes.....	205
	Appendix C—Equations of Elastic and Piezoelectric Constants for Rotation of Axes about the <i>X</i> Axis.....	247
VII.	Theoretical Analysis of Modes of Vibration for Isotropic Rectangular Plates Having All Surfaces Free, by H. J. McSkimin.....	249
VIII.	Principles of Mounting Quartz Plates, by R. A. Sykes.....	276
	Appendix D—Location of Mass on Supporting Wire.....	287
IX.	Sawing, Grinding and Lapping, by W. L. Bond.....	290
X.	Adjusting to Frequency, by G. M. Thurston.....	317
XI.	Metal Electrodes Deposited on Quartz Crystals by the Evaporation Process, by H. W. Weinhart and H. G. Wehe.....	333
XII.	Piezoelectric Crystals in Oscillator Circuits, by I. E. Fair.....	356
XIII.	The Mounting and Fabrication of Plated Quartz Crystal Units, by R. M. C. Greenidge.....	412
XIV.	Effects of Manufacturing Deviations on Crystal Units for Filters, by A. R. d'Heedene.....	436
XV.	The Measurement of the Performance Index of Quartz Plates, by C. W. Harrison.....	458
XVI.	The Wire Mounted Crystal Unit, by William F. Drews and Andrew E. Swickard.....	493
XVII.	Low Frequency Quartz Crystal Cuts Having Low Temperature Coefficients, by W. P. Mason and R. A. Sykes.....	537